



















KIT








	    	  		
	   			
	 x2  x1	 x1  x1  x1  x1		
	 4x35 x4  S6 x4	 3,5x9,5 x2  x2	 4,5x60 x1  4x35 x1  3,9x19 x1  x4  x1  x1	
	 x1	 x1	 x1	 x1
	H	KIT		











3





4




5




6




7




1°



2°






3°






4°




8






9






10






11







12





13



14



15



A line drawing illustrating the application of adhesive to the frame of a glass door. A tube of adhesive is shown dispensing a bead of adhesive into the channel of the frame. An upward-pointing arrow indicates the direction of the adhesive application.

[illegible]

